

+ ADDITIONAL FOAM WITH OPTIONAL CABLES

CABLES INCLUDED

GO2109	PWM POWER PLUS (5 PIN) wiring	✓
GO2110	PWM SIGNAL wiring	✓
GO2111	PIEZO ACTIVATOR wiring	✓
GO2112	GLOW PLUG TEST wiring	✓
GO2113	OHM METER wiring	✓
GO2114	DIAGNOSTIC CAN wiring	✓

GO CODE **2120**
1 with 6 pcs.

+ MULTIMETRO PWM WIRING



Acquisition cable, with the function of measuring voltages and analyzing ground-referred PWM signals.

GO CODE **2101**
1 with 1 pcs. 0,25 kg

+ PULSE SENSE WIRING



Acquisition cable, with the function of detecting the signals of inductive components with only the contact of the detection sensor and the display of the operating frequency.

GO CODE **2103**
1 with 1 pcs. 0,25 kg



EXTREMELY SIMPLE TO USE, BECAUSE IT IS ABLE TO CHANGE ITS FUNCTION ACCORDING TO THE CABLE THAT IS CONNECTED TO IT!

+ GROUND TEST WIRING



Acquisition cable, with the function of verifying the correct state of both mechanical (chassis) and electronic (components) mass, with display of the test result.

GO CODE **2102**
1 with 1 pcs. 0,25 kg

+ DC VOLT GENERATOR WIRING



Emulation cable, with the function of generating DC voltage from 0V to 12V for simulating the output of analog sensors with negative ground.

GO CODE **2104**
1 with 1 pcs. 0,25 kg