



LOCKING TOOL FOR CAMSHAFT ADJUSTER, FORD 1.0 ECOBOOST, TIMING CHAIN



FORD



- Built for the new generation 2 Ford 1.0L EcoBoost engines with timing chain from 2018.
- These special tools are only inserted into the holes of the camshaft solenoid valves after the front cover has been fitted.
- Required for adjusting/fixing the camshafts and replacing the timing chain

ATTENTION

The timing belt running in the oil bath was taken out of service and replaced by the timing chain!



APPLICATION

To be used like OEM Ford 303-1661-1, 303-1661-2; Equivalent to OEM numbers 303-1661-3, 2 450 487.
Made of chrome-molybdenum for impact resistance, with black phosphated anti-corrosion coating.

Brand	Model	Engine	Engine code
Ford	C-Max (from 2017)	1.0 I EcoBoost	B7DA, B3DA, B7JA, B7JB, B7JC, B7JE, BZJA, B7DC, MOJA, MOJB, MODC, B3GA, B3GB
	Focus (from 2018)		
	Focus IV (from 2018)		
	Tourneo		
	Transit Connect (from 2017)		
	Puma (from 2019)		
	Fiesta VII (from 2017)		

